

Exhibit 4 - Site Photographs




Figure 2. Knoxville town site in the 1880s (left) and today (right). The current creek bed is on the right side of the road.



Figure 3. Knoxville town site prior to (2001, left) and after (2004, right) tamarisk removal. Note the deeply incised creek bed and lack of riparian vegetation.

Exhibit 4 - Site Photographs




Figure 4. Distribution of perennial pepperweed in the proposed restoration areas.

Exhibit 4 - Site Photographs



Figure 5. Eticuera Creek where it enters the Gamble Ranch. Foreground vegetation on the left bank of the creek includes tamarisk and recently-established willows.

Exhibit 4 - Site Photographs



Figure 6. Eticuera Creek near the confluence with Adams Creek on the Gamble Ranch.